

Inventory Data:

Structure Name	<input type="text" value="#19 Dean Lake Bridge"/>		
Main Highway #	<input type="text" value="N/A"/>	On <input checked="" type="checkbox"/> or Under <input type="checkbox"/> Structure	Service on structure: <input checked="" type="checkbox"/> Navig. Water <input type="checkbox"/> Non-Navig. Water <input type="checkbox"/> Rail <input type="checkbox"/> Road <input checked="" type="checkbox"/> Ped. <input type="checkbox"/> Other
Location description	<input type="text" value="Dean Lake Road, 100m South of Highway 17"/>	Service under	<input type="checkbox"/> Navig. Water <input type="checkbox"/> Non-Navig. Water <input type="checkbox"/> Rail <input type="checkbox"/> Road <input type="checkbox"/> Ped. <input type="checkbox"/> Other
Owner/Custodian	<input type="text" value="Municipality of Huron Shores"/>	LHRS:	<input type="text"/> LHRS offset: <input type="text"/>
MTO Region	<input type="text" value="50 - Northern"/>	Latitude:	<input type="text" value="46 14.6'"/> Longitude: <input type="text" value="83 9'"/>
Regional Engineer	<input type="text"/>	Heritage Designation:	<input type="checkbox"/> Not Cons. <input type="checkbox"/> Cons./not App. <input type="checkbox"/> List/not Desig. <input type="checkbox"/> Desig./not List <input type="checkbox"/> Desig. & List
MTO Area	<input type="text" value="62 - Sault Ste. Marie"/>	Hwy Class:	Freeway <input type="checkbox"/> Arterial <input type="checkbox"/> Collector <input type="checkbox"/> Local <input checked="" type="checkbox"/>
Old County	<input type="text" value="38 - Algoma"/>	Posted Speed	<input type="text" value="15 km/h"/> No. of Lanes <input type="text" value="-"/>
Township	<input type="text" value="Unknown"/>	AADT	<input type="text" value="150"/> % Truck <input type="text" value="10"/>
Structure Type 1	<input type="text" value="33 - Through Truss"/>	Travel Stream	<input type="text"/>
Structure Material 1	<input type="text"/>	Traffic Directional Bound	<input type="text" value="N to S"/>
Structure Type 2	<input type="text"/>	Inspection Route Sequence	<input type="text"/>
Structure Material 2	<input type="text"/>	Inspection Frequency	<input type="text" value="2"/> (years)
Total Deck Length	<input type="text" value="111.2"/> (m)	Inspection Year	<input type="text" value="2021"/>
Overall Str. Width	<input type="text" value="4.9"/> (m)	Inspection Duration	<input type="text"/> (hrs)
Culvert length	<input type="text"/> (m)	Interchange Number	<input type="text"/>
Total Deck Area	<input type="text" value="544.8"/> (sq.m)	Interchange Structure Number	<input type="text"/>
Roadway Width	<input type="text" value="4.0"/> (m)	Min. Vertical Clearance	<input type="text" value="5.5"/> (m)
Skew Angle	<input type="text" value="0"/> (Degree)	Detour Distance	<input type="text" value="17.4"/> (km)
No. of Spans	<input type="text" value="3"/>	Fill on Structure	<input type="text" value="0"/> (m)
Span Lengths	<input type="text" value="37.0+/-"/> (m)		
<u>For retaining wall:</u>			
Total Wall Length	<input type="text"/> (m)	Max. Wall Height	<input type="text"/> (m)
Total Wall Area	<input type="text"/> (sq.m)	Ave. Wall Height	<input type="text"/> (m)
		Angle of Backfill	<input type="text"/> (Degree)

Rev 2018

Rev 2018

Rev 2018

Historical Data:			
Year Built	<input type="text" value="1908"/>	Year of superstruct. constructed	<input type="text" value="N/A"/>
Last Reg OSIM Inspection	<input type="text" value="2019"/>	Year of Last Minor Rehab.	<input type="text" value="N/A"/>
Last Enh. OSIM Inspection	<input type="text" value="2019"/>	Year of Last Major Rehab.	<input type="text" value="2008"/>
	<input type="text"/>	Current Load Limit	<input type="text" value="10"/> / / <input type="text"/> (tonnes)
<p>Work History: (Date/description) 2008 - Rehabilitation (Beams replaced and RFP deck installed, bridge painted, bracing under deck removed.)</p>			
<p>Investigation History: (Date/description) Detailed structural review completed in 2019 - 10 tonne load posting.</p>			

Scheduled Improvements:	
Regional Priority Number <input type="text"/>	Programmed Work Year <input type="text"/>
Nature of Program Work:	

Appraisal Indices:	Comments
Fatigue	
Seismic	
Scour	
Flood	
Barrier	
Curb	
Load Capacity	

Rev2008
2018

Field Inspection Information:			
Date of Inspection:	2023-07-21	Type of Inspection:	<input checked="" type="checkbox"/> Reg. OSIM <input type="checkbox"/> Enh. OSIM
Inspected By:	Matt Kirby, P. Eng		
Others in Party:	Danny McNeil, P. Eng / Matt Tremelling - Inspector Assistant		
Enh. Access Equipment:	Hammer, measuring tape, camera		
Special Access Equipment:			
Weather:	Sun/Clouds	Temperature:	20 C

2008

Additional Investigations Required:	Priority		
	None	Normal	Urgent
Material Condition Survey	X		
Detailed Deck Condition Survey:			X
Non-destructive Delamination Survey of Asphalt-Covered Deck:	X		
Concrete Substructure Condition Survey:			X
Detailed Coating Condition Survey:	X		
Detailed Timber Investigation	X		
Post-Tensioned Strand Investigation	X		
Underwater Investigation:	X		
Fatigue Investigation:	X		
Seismic Investigation:	X		
Structure Evaluation:		X	
Monitoring	X		
Deformations, Settlements and Movements:		X	
Crack Widths:		X	
RSS Horizontal movements of face:	X		
RSS Vertical movements of overall structure:	X		
RSS Local movements or deterioration of facing elements:	X		
RSS Horizontal movements within overall structure:	X		
RSS Vertical movements within overall structure:	X		
RSS Lateral earth pressure at the back of facing elements:	X		
Investigation Notes: Structure evaluation/Steel Condition Survey completed August of 2019.			

2018

Overall Structure Notes:	
Recommended Work on Structure:	<input type="checkbox"/> None <input type="checkbox"/> Minor Rehab. <input checked="" type="checkbox"/> Major Rehab. <input type="checkbox"/> Replace
Timing of Recommended Work:	<input checked="" type="checkbox"/> 1 to 5 years <input type="checkbox"/> 6 to 10 years
Overall Comments:	Bridge requires minor maintenance items within a year plus plans for major rehab staged over the next 3 years.
Date of Next Inspection:	2024

Rev
2008

Suspected Performance Deficiencies

- | | | |
|--|---|--|
| 01 Load carrying capacity | 06 Bearing not uniformly loaded/unstable | 12 Slippery surfaces |
| 02 Excessive deformations (deflections & rotations) | 07 Jammed expansion joint | 13 Flooding/channel blockage |
| 03 Continuing settlement | 08 Pedestrian/vehicular hazard | 14 Undermining of foundation |
| 04 Continuing movements | 09 Rough riding surface | 15 Unstable embankments |
| 05 Seized bearings | 10 Surface ponding | 16 Other performance deficiencies |
| | 11 Deck/Wall drainage | |

Maintenance Needs

- | | | |
|------------------------------------|-------------------------------------|---|
| 01 N/A | 07 Structural Steel Repair | 13 Erosion Control at Bridges |
| 02 Bridge Cleaning | 08 Concrete Repair | 14 Concrete Sealing |
| 03 Railing System Repair | 09 Timber Repair | 15 N/A |
| 04 N/A | 10 Works for Modular bridges | 16 Works for Drainage System |
| 05 Bridge Deck Joint Repair | 11 Animal/Pest Control | 17 Sealing (Loose Concrete or ACR Steel) |
| 06 N/A | 12 Bridge Surface Repair | 18 Other Maintenance |

2018

Rev
2008

Element Data

Element Group:	Decks	Length:	111.2 m			
Element Name:	Wearing Surface	Width:	4.13 m			
Location:	Deck Surface	Height:	0.0 m			
Material:	Asphalt	Count:	1			
Element Type:		Total Quantity:	459.3 sq.m			
Environment:	Benign / Moderate / Severe	Inspected:	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>	Limited <input type="checkbox"/>	
Protection System:						Perform. Deficiencies
Condition Data:	Units m ² / each / % / all	Exc.	Good	Fair	Poor*	
			358.0	70.0	31.3	09
Comments: Light deck wear throughout, light to medium transverse cracking, localized delamination at deck joints, patches at intermediate deck joints, patches and wheel rutting at northern span, localized potholes.						
Recommended Work:			<input checked="" type="checkbox"/> Rehab <input type="checkbox"/> Replace <input checked="" type="checkbox"/> 1-5 years <input type="checkbox"/> 6-10 years		Maintenance Needs: 01. N/A	
Repair deck slab wearing surface					<input type="checkbox"/> Urgent <input type="checkbox"/> 1 year <input type="checkbox"/> 2 year	

Rev2008

Rev2008



Patches, Wheel Rutting and Ponding Water on North Span

Element Data

Element Group:	Decks	Length:	111.2 m			
Element Name:	Deck Top	Width:	4.13 m			
Location:		Height:	0.13 m			
Material:	Fiberglass wrapped timber deck	Count:	1			
Element Type:		Total Quantity:	459.3 sq.m			
Environment:	Benign Moderate Severe	Inspected:	Yes <input type="checkbox"/>	No <input type="checkbox"/>	Limited <input checked="" type="checkbox"/>	
Protection System:	Fibreglass					Perform. Deficiencies
Condition Data:	Units m ² / each / % / all	Exc.	Good	Fair	Poor*	
			439.3	10	10	11
Comments: Light to medium transverse cracking, localized delamination at deck joints and light wear throughout. Active wet areas. Deck joints in poor condition.						
Recommended Work:			Maintenance Needs:			
None			01. N/A			
			<input type="checkbox"/> Urgent <input type="checkbox"/> 1 year <input type="checkbox"/> 2 year			

Rev2008

Rev2008



Large Potholes, De-bonding and Transverse Cracking in Overlay

Element Data

Element Group:	Decks	Length:	2.00 m			
Element Name:	Soffit	Width:	3.50 m			
Location:	Ends	Height:	-			
Material:	Timber/Fiberglass Composite	Count:	2			
Element Type:		Total Quantity:	14 sq.m			
Environment:	Benign Moderate Severe	Inspected:	Yes <input type="checkbox"/>	No <input type="checkbox"/>	Limited <input checked="" type="checkbox"/>	
Protection System:						Perform. Deficiencies
Condition Data:	Units m² / each / % / all	Exc.	Good	Fair	Poor*	
			7	7		00. None
Comments: Water staining present, difficult to know if staining is epoxy within the panels or on the soffit surface.						
Recommended Work:			Maintenance Needs:			
<input type="checkbox"/> Rehab <input type="checkbox"/> Replace <input type="checkbox"/> 1-5 years <input type="checkbox"/> 6-10 years			<input type="checkbox"/> Urgent <input type="checkbox"/> 1 year <input type="checkbox"/> 2 year			
None						

Rev2008

Rev2008



Typical Deck Soffit End

Element Data

Element Group:	Decks	Length:	109.2 m			
Element Name:	Soffit	Width:	2.50 m			
Location:	Interior	Height:	-			
Material:	Timber/Fiberglass Composite	Count:	1			
Element Type:		Total Quantity:	273.0 sq.m			
Environment:	Benign / Moderate / Severe	Inspected:	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>	Limited <input checked="" type="checkbox"/>	
Protection System:						Perform. Deficiencies
Condition Data:	Units m ² / each / % / all	Exc.	Good	Fair	Poor*	
			91	91	91	00. None
Comments: Fiberglass has localized loss of resin directly below deck panel joint. Typical at all panel joint locations.						
Recommended Work:			Maintenance Needs:			
None			01. N/A			
			<input type="checkbox"/> Urgent <input type="checkbox"/> 1 year <input type="checkbox"/> 2 year			

Rev2008

Rev2008



Deck Soffit General Arrangement (looking north)

Element Data

Element Group:	Decks	Length:	109.2 m			
Element Name:	Soffit	Width:	0.50 m			
Location:	Exterior	Height:	-			
Material:	Timber/Fiberglass Composite	Count:	2			
Element Type:		Total Quantity:	109.2 sq. m			
Environment:	Benign <u>Moderate</u> Severe	Inspected:	Yes <input type="checkbox"/>	No <input type="checkbox"/>	Limited <input checked="" type="checkbox"/>	
Protection System:						Perform. Deficiencies
Condition Data:	<u>m²</u> m / each / % / all	Exc.	Good	Fair	Poor*	
			36.4	36.4	36.4	00. None
Comments:						
Two most northern deck panels were found to have water residing within the panels (2019). All other panels had no traces of moisture.						
Recommended Work:			Maintenance Needs:			
<input type="checkbox"/> Rehab <input type="checkbox"/> Replace <input type="checkbox"/> 1-5 years <input type="checkbox"/> 6-10 years			01. N/A <input type="checkbox"/> Urgent <input type="checkbox"/> 1 year <input type="checkbox"/> 2 year			
None						

Rev2008

Rev2008



Element Data

Element Group:	Beams/MLE's	Length:	2.0 m (Average)			
Element Name:	Stringers	Width:	-			
Location:	Ends	Height:	.21			
Material:	Steel	Count:	24			
Element Type:	I Type	Total Quantity:	24 (each)			
Environment:	Benign <u>Moderate</u> Severe	Inspected:	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>	Limited <input checked="" type="checkbox"/>	
Protection System:	Painted					Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*	Perform. Deficiencies
	m ² / m <u>each</u> % / all			20	4	
Comments: Localized medium to severe corrosion at abutment/pier bearing locations with perforations noted at south and north abutments (east sides only).						
Recommended Work:			Maintenance Needs:			
<input checked="" type="checkbox"/> Rehab <input type="checkbox"/> Replace <input checked="" type="checkbox"/> 1-5 years <input type="checkbox"/> 6-10 years Steel reinforcing required within 1 year.			01. N/A <input type="checkbox"/> Urgent <input type="checkbox"/> 1 year <input type="checkbox"/> 2 year			



Localized Severe Corrosion and Cracking in Web of Exterior Stringer at North Abutment

Element Data

Element Group:	Beams/MLE	Length:	33 m			
Element Name:	Stringers	Width:	-			
Location:	Middle	Height:	0.21 m			
Material:	Steel	Count:	12			
Element Type:	I Type	Total Quantity:	12 (each)			
Environment:	Benign / Moderate / Severe	Inspected:	Yes <input type="checkbox"/>	No <input type="checkbox"/>	Limited <input checked="" type="checkbox"/>	
Protection System:	Painted					Perform. Deficiencies
Condition Data:	Units m ² / m (each) % / all	Exc.	Good	Fair	Poor*	
				12		00. None
Comments: Localized medium to severe corrosion at connection locations. Light corrosion throughout. Crack at bearing plates where the stringer sits on the transverse floor beam on the west exterior stringer at the first vertical from the north pier.						
Recommended Work:			Maintenance Needs: 07. Structural Steel Repair			
<input type="checkbox"/> Rehab <input type="checkbox"/> Replace <input type="checkbox"/> 1-5 years <input type="checkbox"/> 6-10 years			<input checked="" type="checkbox"/> Urgent <input type="checkbox"/> 1 year <input type="checkbox"/> 2 year			
None			Repair Cracked weld			

Rev2008

Rev2008



Steel Stringers within Middle Sections

Element Data

Element Group:	Beams/MLE	Length:	0.15 m			
Element Name:	Floor Beams	Width:	0.50 m			
Location:	Ends	Height:	0.46 m			
Material:	Steel	Count:	36			
Element Type:	I Type	Total Quantity:	21.8 sq.m			
Environment:	Benign / Moderate / Severe	Inspected:	Yes <input type="checkbox"/>	No <input type="checkbox"/>	Limited <input checked="" type="checkbox"/>	
Protection System:	Painted					Perform. Deficiencies
Condition Data:	Units m ² / each / % / all	Exc.	Good	Fair	Poor*	
				19.2	2.6	00. None
Comments: Light to medium corrosion, localized rust jacking at floor beam to truss vertical connection(s), Top flange has severe localized corrosion, pitting and staining.						
Recommended Work:			Maintenance Needs:			
None			01. N/A			
			<input type="checkbox"/> Rehab <input type="checkbox"/> Replace <input type="checkbox"/> 1-5 years <input type="checkbox"/> 6-10 years <input type="checkbox"/> Urgent <input type="checkbox"/> 1 year <input type="checkbox"/> 2 year			

Rev2008

Rev2008



Typical Floor Beam - Pitting and Flaking Present on End Sections

Element Data

Element Group:	Beams/MLE	Length:	0.2 m			
Element Name:	Floor Beams	Width:	3.83 m			
Location:	Middle	Height:	0.46 m			
Material:	Steel	Count:	18			
Element Type:	I Type	Total Quantity:	83.4 sq.m			
Environment:	Benign / Moderate / Severe	Inspected:	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>	Limited <input checked="" type="checkbox"/>	
Protection System:	Painted					Perform. Deficiencies
Condition Data:	Units m ² m / each / % / all	Exc.	Good	Fair	Poor*	
				81.3	2.1	00. None
Comments: Light to medium corrosion throughout, Top flange has moderate to severe localized corrosion and pitting.						
Recommended Work:			Maintenance Needs:			
<input type="checkbox"/> Rehab <input type="checkbox"/> Replace <input type="checkbox"/> 1-5 years <input type="checkbox"/> 6-10 years			<input type="checkbox"/> Urgent <input type="checkbox"/> 1 year <input type="checkbox"/> 2 year			
None.			01. N/A			

Rev2008

Rev2008



Staining of Floor Beams at Edges of Deck (staining below shim plates under exterior stringers)

Element Data

Element Group:	Piers	Length:	1.30 m			
Element Name:	Shafts/Columns/Pile Bents	Width:	6.20 m			
Location:	Intermediate Piers	Height:	4.44 m			
Material:	Concrete	Count:	2			
Element Type:	Concrete Shafts/Pier Walls	Total Quantity:	133.2 sq.m			
Environment:	Benign Moderate Severe	Inspected:	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>	Limited <input checked="" type="checkbox"/>	
Protection System:						Perform. Deficiencies
Condition Data:	Units m² / each / % / all	Exc.	Good	Fair	Poor*	
				117.2	16	00. None
Comments: Medium scaling, medium to wide cracking with staining, localized spall at South pier bearing, localized spalls in pier faces. Delaminations noted throughout.						
Recommended Work:			Maintenance Needs:			
None			01. N/A			
			<input type="checkbox"/> Urgent <input type="checkbox"/> 1 year <input type="checkbox"/> 2 year			




Typical Pier With Localized Spalling and Medium to Wide Cracking Throughout

Element Data

Element Group:	Piers	Length:	-			
Element Name:	Bearings	Width:	-			
Location:	Intermediate Piers	Height:	-			
Material:	Other	Count:	4			
Element Type:	Elastomeric Pads	Total Quantity:	4 (each)			
Environment:	Benign / Moderate / Severe	Inspected:	Yes <input type="checkbox"/>	No <input type="checkbox"/>	Limited <input checked="" type="checkbox"/>	
Protection System:						Perform. Deficiencies
Condition Data:	Units m ² / m (each) % / all	Exc.	Good	Fair	Poor*	
				3	1	00. None
Comments: Light weathering of steel bearing plates. Rubber pads have light bulge when felt by hand. Undermining of the bearing plate at the west side of south pier (upstream side). This may be causing the deck elevation difference at the joint.						
Recommended Work:			Maintenance Needs:			
<input checked="" type="checkbox"/> Rehab <input type="checkbox"/> Replace <input checked="" type="checkbox"/> 1-5 years <input type="checkbox"/> 6-10 years Jacking and stabilizing the undermining of the bearing plate/pad.			01. N/A <input type="checkbox"/> Urgent <input type="checkbox"/> 1 year <input type="checkbox"/> 2 year			

Rev2008

Rev2008



Pier Bearings General Arrangement (South Pier)

Element Data

Element Group:	Piers	Length:	-			
Element Name:	Bearings	Width:	-			
Location:	Intermediate Piers	Height:	-			
Material:	Steel	Count:	4			
Element Type:	Plate	Total Quantity:	4 (each)			
Environment:	Benign / Moderate / Severe	Inspected:	Yes <input type="checkbox"/>	No <input type="checkbox"/>	Limited <input checked="" type="checkbox"/>	
Protection System:						Perform. Deficiencies
Condition Data:	Units m ² / m (each) % / all	Exc.	Good	Fair	Poor*	
				4		00. None
Comments: Light to medium corrosion throughout, severe localized corrosion and minor rust jacking.						
Recommended Work:			Maintenance Needs:			
None.			01. N/A			
			<input type="checkbox"/> Urgent <input type="checkbox"/> 1 year <input type="checkbox"/> 2 year			

Rev2008

Rev2008



Typical Pier Bearing (North Pier)

Element Data

Element Group:	Trusses/Arches		Length:	111.20 m		
Element Name:	Bottom Chord		Width:	0.10 m		
Location:			Height:	0.15 m		
Material:	Steel		Count:	2		
Element Type:	T-type		Total Quantity:	111.2 sq. m		
Environment:	Benign / Moderate / Severe		Inspected:	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Limited <input checked="" type="checkbox"/>		
Protection System:	Painted					Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*	
	m² m / each / % / all			89.0	22.2	01
Comments:						
Moderate to severe corrosion with flaking, gravel and debris noted on bottom chords, localized rust jacking at gusset plates and angle connection. Severely corroded rivets/bolts.						
Recommended Work:			Maintenance Needs:			
<input type="checkbox"/> Rehab <input type="checkbox"/> Replace <input type="checkbox"/> 1-5 years <input type="checkbox"/> 6-10 years			02. Bridge Cleaning <input type="checkbox"/> Urgent <input checked="" type="checkbox"/> 1 year <input type="checkbox"/> 2 year			
None			Clean gravel and debris from bottom chord members/plating.			

Rev2008

Rev2008



Typical Bottom Chord - Double angles

Element Data

Element Group:	Trusses/Arches		Length:	128.7 m		
Element Name:	Top Chord		Width:	0.36 m		
Location:			Height:	0.20 m		
Material:	Steel		Count:	2		
Element Type:	Box/Trapezoidal		Total Quantity:	285.7 sq.m		
Environment:	Benign / Moderate / Severe		Inspected:	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Limited <input checked="" type="checkbox"/>		
Protection System:	Painted					Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*	
	m ² / each / % / all			284.0	1.7	00. None
Comments:						
Light to medium corrosion throughout. Light corrosion on rivets. Small localized areas of impact damage from oversized vehicles were noted in the structure. Some instances of damage to the inside surface of the top chord appeared new and some damages appeared to have been previously coated over top of.						
Recommended Work:			Maintenance Needs:			
None			01. N/A			
			<input type="checkbox"/> Urgent <input type="checkbox"/> 1 year <input type="checkbox"/> 2 year			



Top Chord - Built up Box Section. Various locations with impact damage to the interior edges.

Element Data

Element Group:	Trusses/Arches		Length:	varies		
Element Name:	Vertical/Diagonals		Width:	varies		
Location:			Height:	varies		
Material:	Steel		Count:			
Element Type:	T-type		Total Quantity:	392.6 sq.m		
Environment:	Benign / Moderate / Severe		Inspected:	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>		Limited <input checked="" type="checkbox"/>
Protection System:	Hot dip galvanizing					Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*	
	m ² / each / % / all			352.6	40	00. None
Comments:						
Light to moderate corrosion with flaking and isolated rust jacking, 1st and 2nd diagonal of South span on East truss have minor localized bends, 1st diagonal from the North end of the west Abutment has local distortion. Uncertain if this was from an impact load or an overloading scenario. 3rd vertical from South on West truss in the 2nd span has localized impact damage at guiderail.						
Recommended Work:			<input checked="" type="checkbox"/> Rehab <input type="checkbox"/> Replace <input checked="" type="checkbox"/> 1-5 years <input type="checkbox"/> 6-10 years		Maintenance Needs:	
Monitor with yearly inspections					01. N/A <input type="checkbox"/> Urgent <input type="checkbox"/> 1 year <input type="checkbox"/> 2 year	




Localized distortion of diagonal (inner) on the West Truss at North Abutment

Rev2008

Rev2008

Element Data

Element Group:	Trusses/Arches		Length:	-		
Element Name:	Connections		Width:	-		
Location:			Height:	-		
Material:			Count:	72		
Element Type:			Total Quantity:	72 (each)		
Environment:	Benign / Moderate / Severe		Inspected:	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Limited <input checked="" type="checkbox"/>		
Protection System:						Perform. Deficiencies
Condition Data:	Units m ² / m (each) % / all	Exc.	Good	Fair 58	Poor* 14	02. Excessive Deform
Comments: Light to medium corrosion with flaking and rust jacking, severe corrosion with pitting observed at the SW and SE bearing, gravel/debris noted on connections and on bottom chord, perforations at North and South pier, East and West truss, moderate to severely corroded rivets at all connection locations.						
Recommended Work:			Maintenance Needs:			
<input type="checkbox"/> Rehab <input type="checkbox"/> Replace <input type="checkbox"/> 1-5 years <input type="checkbox"/> 6-10 years None			02. Bridge Cleaning <input type="checkbox"/> Urgent <input checked="" type="checkbox"/> 1 year <input type="checkbox"/> 2 year Cleaning of gravel and debris from connections			



Moderate to Severe Corrosion of Rivets and Gusset plates.

Element Data

Element Group:	Bracing		Length:	-		
Element Name:	Bracing		Width:	-		
Location:			Height:	-		
Material:			Count:	33		
Element Type:			Total Quantity:	33 (each)		
Environment:	Benign / Moderate / <u>Severe</u>		Inspected:	Yes <input type="checkbox"/> No <input type="checkbox"/> Limited <input type="checkbox"/>		
Protection System:	Hot dip galvanizing					Perform. Deficiencies
Condition Data:	Units		Exc.	Good	Fair	Poor*
	m ² / m	<u>each</u> % / all			31	2
Comments: No significant change to the top chord bracing at the South end of North span (localized bends, flaking of coating with light corrosion evident). Two rivets loose in top chord of connection.						
Recommended Work:			Maintenance Needs:			
None			01. N/A			
			<input type="checkbox"/> Urgent <input type="checkbox"/> 1 year <input type="checkbox"/> 2 year			

Rev2008

Rev2008



Warping of Vertical near connection to 'K' bracing

Element Data

Element Group:	Embankments and Streams	Length:	-			
Element Name:	Slope Protection	Width:	-			
Location:	Northwest Quadrant	Height:	-			
Material:	Blasted Rock	Count:	1			
Element Type:		Total Quantity:	1 (each)			
Environment:	Benign / Moderate / Severe	Inspected:	Yes <input type="checkbox"/>	No <input type="checkbox"/>	Limited <input type="checkbox"/>	
Protection System:						Perform. Deficiencies
Condition Data:	Units m ² / m (each) % / all	Exc.	Good 1	Fair	Poor*	Perform. Deficiencies 00. None
Comments: Rock protection in NW quadrant is in good condition with no evidence of erosion.						
Recommended Work:			Maintenance Needs:			
None.			01. N/A			
			<input type="checkbox"/> Urgent <input type="checkbox"/> 1 year <input type="checkbox"/> 2 year			

Rev2008

Rev2008



Rock Protection on NW Embankment

Element Data

Element Group:	Joints		Length:	-		
Element Name:	Armouring/Retaining Devices		Width:	4.03 m		
Location:	Ends of Deck Spans		Height:	-		
Material:	Steel		Count:	4		
Element Type:			Total Quantity:	16.1 m		
Environment:	Benign / Moderate / Severe		Inspected:	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Limited <input checked="" type="checkbox"/>		
Protection System:	Hot dip galvanizing					Perform. Deficiencies
Condition Data:	Units m ² (m) each / % / all	Exc.	Good	Fair	Poor*	Perform. Deficiencies
			12.0	4.1		00. None
Comments: Light to moderate wear with localized light corrosion. The second armouring plate from the South pier has lifted slightly, allowing gravel and debris underneath the plate.						
Recommended Work:			<input checked="" type="checkbox"/> Rehab <input type="checkbox"/> Replace <input checked="" type="checkbox"/> 1-5 years <input type="checkbox"/> 6-10 years		Maintenance Needs: 02. Bridge Cleaning	
Rehab/reconnect armouring steel					<input type="checkbox"/> Urgent <input checked="" type="checkbox"/> 1 year <input type="checkbox"/> 2 year Cleaning of gravel debris from connections.	

Rev2008

Rev2008



Lifted Armouring Plate at Centerline, Rotated at West side of Bridge

Element Data

Element Group:	Joints		Length:	0.30 m		
Element Name:	Concrete end dams		Width:	6.40 m		
Location:	Abutments		Height:	-		
Material:	Concrete		Count:	2		
Element Type:			Total Quantity:	3.8 sq.m		
Environment:	Benign / Moderate / Severe		Inspected:	Yes <input type="checkbox"/> No <input type="checkbox"/> Limited <input checked="" type="checkbox"/>		
Protection System:						Perform. Deficiencies
Condition Data:	Units m ² m / each / % / all	Exc.	Good	Fair	Poor*	
			3.8			00. None
Comments: Light abrasions and wear, asphalt patching over South end dam.						
Recommended Work:			Maintenance Needs:			
None			01. N/A			
			<input type="checkbox"/> Urgent <input type="checkbox"/> 1 year <input type="checkbox"/> 2 year			

Rev2008

Rev2008



Typical Concrete End Dam

Element Data

Element Group:	Joints		Length:	-		
Element Name:	Seals/Sealant		Width:	-		
Location:			Height:	-		
Material:	Other		Count:	6		
Element Type:	Strip Seal		Total Quantity:	6 (each)		
Environment:	Benign / Moderate / Severe		Inspected:	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Limited <input checked="" type="checkbox"/>		
Protection System:						Perform. Deficiencies
Condition Data:	Units m ² / m (each) % / all	Exc.	Good	Fair	Poor*	
					6	07
Comments: Light to severe cracking and separation of seals at bridge deck joints, light to wide cracking with patching observed at the deck joints. Sections of seals missing on mid-span.						
Recommended Work:			Maintenance Needs:			
<input type="checkbox"/> Rehab <input checked="" type="checkbox"/> Replace <input checked="" type="checkbox"/> 1-5 years <input type="checkbox"/> 6-10 years			01. N/A			
Replace bridge deck joints/seals.			<input type="checkbox"/> Urgent <input type="checkbox"/> 1 year <input type="checkbox"/> 2 year			



Joint Seal Severely Deteriorated with Sections Missing

Element Data

Element Group:	Abutments	Length:	-			
Element Name:	Abutment Walls	Width:	7.47 m			
Location:	North and South Ends of Bridge	Height:	4.80 m			
Material:	Concrete	Count:	2			
Element Type:	Conventional Closed	Total Quantity:	71.7 sq. m			
Environment:	Benign Moderate Severe	Inspected:	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>	Limited <input checked="" type="checkbox"/>	
Protection System:						Perform. Deficiencies
Condition Data:	Units m² m / each / % / all	Exc.	Good	Fair	Poor*	
					71.7	00. None
Comments: Stained narrow to wide map cracking with efflorescence, delamination, light to severe scaling, gravel/debris buildup and spalls.						
Recommended Work:			<input checked="" type="checkbox"/> Rehab <input type="checkbox"/> Replace <input checked="" type="checkbox"/> 1-5 years <input type="checkbox"/> 6-10 years		Maintenance Needs: 01. N/A	
Partial depth concrete repairs to abutment walls					<input type="checkbox"/> Urgent <input type="checkbox"/> 1 year <input type="checkbox"/> 2 year	

Rev2008

Rev2008



Severe Spalling, Delamination and Efflorescence Throughout Abutment Walls

Element Data

Element Group:	Abutments	Length:	0.30 m			
Element Name:	Ballast Walls	Width:	7.70 m			
Location:	North and South Ends of Bridge	Height:	0.46 m			
Material:	Concrete	Count:	2			
Element Type:		Total Quantity:	7.1 sq. m			
Environment:	Benign <u>Moderate</u> Severe	Inspected:	Yes <input type="checkbox"/>	No <input type="checkbox"/>	Limited <input checked="" type="checkbox"/>	
Protection System:						Perform. Deficiencies
Condition Data:	<u>m²</u> m / each / % / all	Exc.	Good	Fair	Poor*	00. None
Comments: Light pop-outs, moderate spall Northwest Quadrant.						
Recommended Work:			Maintenance Needs:			
None			01. N/A			
			<input type="checkbox"/> Urgent <input type="checkbox"/> 1 year <input type="checkbox"/> 2 year			

Rev2008

Rev2008

Element Data

Element Group:	Abutments	Length:	-			
Element Name:	Wingwalls	Width:	4.90 m			
Location:	4 Corners of the Abutments	Height:	4.40 m			
Material:	Concrete	Count:	4			
Element Type:	Mass Concrete	Total Quantity:	86.2 sq.m			
Environment:	Benign <u>Moderate</u> Severe	Inspected:	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>	Limited <input checked="" type="checkbox"/>	
Protection System:						Perform. Deficiencies
Condition Data:	<u>m²</u> m / each / % / all	Exc.	Good	Fair	Poor*	
					86.2	00. None
Comments: Stained narrow to wide map cracking with efflorescence, delamination, light to severe scaling and spalls.						
Recommended Work:			Maintenance Needs:			
<input checked="" type="checkbox"/> Rehab <input type="checkbox"/> Replace <input checked="" type="checkbox"/> 1-5 years <input type="checkbox"/> 6-10 years Partial depth concrete repairs to abutment wingwalls.			01. N/A <input type="checkbox"/> Urgent <input type="checkbox"/> 1 year <input type="checkbox"/> 2 year			

Rev2008

Rev2008



Delaminations and Efflorescence Throughout Wingwalls

Element Data

Element Group:	Abutments		Length:	-		
Element Name:	Bearings		Width:	-		
Location:	North and South Ends of Bridge		Height:	-		
Material:	Other		Count:	4		
Element Type:	Elastomeric Pads		Total Quantity:	4 (each)		
Environment:	Benign <u>Moderate</u> Severe		Inspected:	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Limited <input checked="" type="checkbox"/>		
Protection System:						Perform. Deficiencies
Condition Data:	Units m ² / m <u>each</u> % / all	Exc.	Good 4	Fair	Poor*	00. None
Comments: Gravel and dirt debris buildup at bearings/pads. Bearing pads are generally in good condition with light bulging and shear deformation						
Recommended Work:			Maintenance Needs:			
<input type="checkbox"/> Rehab <input type="checkbox"/> Replace <input type="checkbox"/> 1-5 years <input type="checkbox"/> 6-10 years None			02. Bridge Cleaning <input type="checkbox"/> Urgent <input checked="" type="checkbox"/> 1 year <input type="checkbox"/> 2 year Clean bearing seats free of gravel/debris			

Rev2008

Rev2008

Element Data

Element Group:	Approaches	Length:	6.0 m			
Element Name:	Barriers	Width:	-			
Location:	East and West Edges of Approaches	Height:	-			
Material:	Steel	Count:	4			
Element Type:	Steel Flex Beam on Wood Posts	Total Quantity:	24.0 m			
Environment:	Benign / Moderate / Severe	Inspected:	Yes <input type="checkbox"/>	No <input type="checkbox"/>	Limited <input type="checkbox"/>	
Protection System:						Perform. Deficiencies
Condition Data:	Units m ² (m) each / % / all	Exc.	Good	Fair	Poor*	
				6.0	18.0	01.
Comments: Vehicular damage to barrier at SW quadrant, missing guiderail bolts, moderate to severe decay of wood posts, wide splits and checks with severe end decay, buried end treatments at approach guiderails on the south approach.						
Recommended Work:			<input checked="" type="checkbox"/> Rehab <input type="checkbox"/> Replace <input checked="" type="checkbox"/> 1-5 years <input type="checkbox"/> 6-10 years		Maintenance Needs: 17. Scaling	
Replace guiderails and upgrade end treatments.					<input type="checkbox"/> Urgent <input checked="" type="checkbox"/> 1 year <input type="checkbox"/> 2 year Replace missing and/or tighten loose bolts in approach guiderails, replace decayed posts.	

Rev2008

Rev2008



Wooden Posts with Moderate to Severe End Decay.

Element Data

Element Group:	Approaches		Length:	6.0 m		
Element Name:	Wearing Surface		Width:	3.70 m		
Location:	North and South Approaches		Height:	-		
Material:	Surface Treatment		Count:	2		
Element Type:			Total Quantity:	44.4 sq.m		
Environment:	Benign / Moderate / Severe		Inspected:	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Limited <input type="checkbox"/>		
Protection System:						Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*	
	m² m / each / % / all			34	10.4	08, 09
Comments: Medium to severe raveling at centerline, medium wheel rutting, light to moderate potholes with patching noted throughout the South approach.						
Recommended Work:			Maintenance Needs: 12. Bridge Surface Repair			
<input type="checkbox"/> Rehab <input checked="" type="checkbox"/> Replace <input checked="" type="checkbox"/> 1-5 years <input type="checkbox"/> 6-10 years Regrade South approach and replace wearing surface			<input type="checkbox"/> Urgent <input checked="" type="checkbox"/> 1 year <input type="checkbox"/> 2 year Surface repairs and patching to smooth out approaches. (South Approach worse)			

Rev2008

Rev2008



Patches and Potholes in South Approach

Element Data

Element Group:	Barriers		Length:	0.09 m		
Element Name:	Posts		Width:	0.09 m		
Location:	East and West Railing System		Height:	1.60 m		
Material:	Steel		Count:	46		
Element Type:			Total Quantity:	46 (each)		
Environment:	Benign / Moderate / Severe		Inspected:	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Limited <input type="checkbox"/>		
Protection System:						Perform. Deficiencies
Condition Data:	Units m ² / m (each) % / all	Exc.	Good 43	Fair 2	Poor* 1	00. None
Comments: Light corrosion of steel posts, localized impact damage of vertical post on West truss of center span.						
Recommended Work: None			<input type="checkbox"/> Rehab <input type="checkbox"/> Replace <input type="checkbox"/> 1-5 years <input type="checkbox"/> 6-10 years		Maintenance Needs: 01. N/A <input type="checkbox"/> Urgent <input type="checkbox"/> 1 year <input type="checkbox"/> 2 year	

Rev2008

Rev2008



Barrier System on Bridge - General Arrangement

Element Data

Element Group:	Barriers	Length:	111.2 m			
Element Name:	Railing Systems	Width:	-			
Location:	East and West Edges of Bridge	Height:	-			
Material:	Steel	Count:	2			
Element Type:	Steel Flex Beam on Steel Posts	Total Quantity:	222.4 m			
Environment:	Benign / Moderate / Severe	Inspected:	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>	Limited <input type="checkbox"/>	
Protection System:	Hot dip galvanizing					Perform. Deficiencies
Condition Data:	Units m ² (m) each / % / all	Exc.	Good	Fair	Poor*	
			202.2	20.2		00. None
Comments: Localized medium impact damage to the railing system, light abrasions and scrapes, light corrosion, loose bolts/nuts.						
Recommended Work:			Maintenance Needs: 07. Structural Steel Repair			
<input type="checkbox"/> Rehab <input type="checkbox"/> Replace <input type="checkbox"/> 1-5 years <input type="checkbox"/> 6-10 years None			<input type="checkbox"/> Urgent <input checked="" type="checkbox"/> 1 year <input type="checkbox"/> 2 year Tighten loose bolts.			

Rev2008

Rev2008



Barrier System General Arrangement

Element Data

Element Group:	Barriers	Length:	111.2 m			
Element Name:	Hand Railings	Width:	-			
Location:	East and West Edges of Bridge	Height:	-			
Material:	Steel	Count:	2			
Element Type:	Steel Railing	Total Quantity:	222.4 m			
Environment:	Benign / Moderate / Severe	Inspected:	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>	Limited <input type="checkbox"/>	
Protection System:						Perform. Deficiencies
Condition Data:	Units m ² (m) each / % / all	Exc.	Good 211.8	Fair 10.6	Poor*	00. None
Comments: Localized medium impact damage with bent retaining plate in the Southwest quadrant of South span, light corrosion throughout noted.						
Recommended Work:			Maintenance Needs:			
<input type="checkbox"/> Rehab <input type="checkbox"/> Replace <input type="checkbox"/> 1-5 years <input type="checkbox"/> 6-10 years None.			01. N/A <input type="checkbox"/> Urgent <input type="checkbox"/> 1 year <input type="checkbox"/> 2 year			



Hand railing with breakdown of protective coating

Rev2008

Rev2008

Element Data

Element Group:	Coatings		Length:	varies		
Element Name:	Railing Systems/Hand Railings		Width:	varies		
Location:	Rail and Posts		Height:	varies		
Material:			Count:	1		
Element Type:			Total Quantity:	250.8 sq.m		
Environment:	Benign / Moderate / Severe		Inspected:	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Limited <input type="checkbox"/>		
Protection System:	Hot dip galvanizing					Perform. Deficiencies
Condition Data:	Units m ² / each / % / all	Exc.	Good 204.0	Fair 25.0	Poor* 20.8	00. None
Comments: Light to complete breakdown of protective coating on railing posts.						
Recommended Work: None			<input type="checkbox"/> Rehab <input type="checkbox"/> Replace <input type="checkbox"/> 1-5 years <input type="checkbox"/> 6-10 years		Maintenance Needs: 01. N/A <input type="checkbox"/> Urgent <input type="checkbox"/> 1 year <input type="checkbox"/> 2 year	



Breakdown of Coating throughout railing/posts.

Rev2008

Rev2008

Element Data

Element Group:	Coatings		Length:	varies		
Element Name:	Structural Steel		Width:	varies		
Location:	Trusses, Diagonals, Bracing, etc.		Height:	varies		
Material:			Count:	1		
Element Type:			Total Quantity:	1526.0 sq. m		
Environment:	Benign / Moderate / Severe		Inspected:	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>		Limited <input checked="" type="checkbox"/>
Protection System:	Hot dip galvanizing					Perform. Deficiencies
Condition Data:	Units m² / each / % / all	Exc.	Good	Fair	Poor*	
			305.0	916.0	305.0	00. None
Comments: Localized breakdown and loss of protective coating throughout						
Recommended Work:			<input checked="" type="checkbox"/> Rehab <input type="checkbox"/> Replace <input type="checkbox"/> 1-5 years <input checked="" type="checkbox"/> 6-10 years		Maintenance Needs: 01. N/A	
Re-coat structural steel					<input type="checkbox"/> Urgent <input type="checkbox"/> 1 year <input type="checkbox"/> 2 year	

Rev2008

Rev2008



Typical Protective Coating Condition

Element Data

Element Group:	Accessories		Length:	-		
Element Name:	Signs		Width:	-		
Location:	Ends of Bridge		Height:	-		
Material:	Steel		Count:	8		
Element Type:			Total Quantity:	8 (each)		
Environment:	Benign / Moderate / Severe		Inspected:	Yes <input type="checkbox"/> No <input type="checkbox"/> Limited <input type="checkbox"/>		
Protection System:						Perform. Deficiencies
Condition Data:	Units m ² / m (each) % / all	Exc.	Good	Fair	Poor*	
			6		4	08
Comments: Load posting signs at both approaches, 4 hazard markers at bridge corners were missing.						
Recommended Work:			Maintenance Needs:			
<input type="checkbox"/> Rehab <input type="checkbox"/> Replace <input type="checkbox"/> 1-5 years <input type="checkbox"/> 6-10 years None			18. Other <input type="checkbox"/> Urgent <input checked="" type="checkbox"/> 1 year <input type="checkbox"/> 2 year Install hazard markers at corners of the bridge & single lane bridge markers at South approach.			

Rev2008

Rev2008



Signs at North Approach

Element Data

Element Group:	Foundations		Length:			
Element Name:	Foundation (below ground level)		Width:			
Location:			Height:			
Material:			Count:			
Element Type:			Total Quantity:	N/A		
Environment:	Benign / Moderate / Severe		Inspected:	Yes <input type="checkbox"/>	No <input type="checkbox"/>	Limited <input checked="" type="checkbox"/>
Protection System:						Perform. Deficiencies
Condition Data:	Units m ² / m / each / % / all	Exc.	Good	Fair	Poor*	00. None
Comments:						
Recommended Work:			Maintenance Needs:			
<input type="checkbox"/> Rehab <input type="checkbox"/> Replace <input type="checkbox"/> 1-5 years <input type="checkbox"/> 6-10 years			<input type="checkbox"/> Urgent <input type="checkbox"/> 1 year <input type="checkbox"/> 2 year 01. N/A			

Rev2008

Rev2008

Element Data

Element Group:	Embankments and Streams	Length:	-			
Element Name:	Embankments	Width:	-			
Location:	4 Corners of the Bridge	Height:	-			
Material:	Vegetation	Count:	4			
Element Type:		Total Quantity:	4 (each)			
Environment:	<input checked="" type="checkbox"/> Benign / <input type="checkbox"/> Moderate / <input type="checkbox"/> Severe	Inspected:	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Limited			
Protection System:						Perform. Deficiencies
Condition Data:	Units m ² / m <input checked="" type="checkbox"/> each % / all	Exc.	Good	Fair	Poor*	
			3	1		00. None
Comments: Vegetated embankments were generally in good condition. Vegetation is overgrown on Northeast quadrant. Northwest embankment has rock protection. Moderate scour noted to the northeast abutment embankment at the foundation level.						
Recommended Work:			Maintenance Needs:			
<input type="checkbox"/> Rehab <input type="checkbox"/> Replace <input type="checkbox"/> 1-5 years <input type="checkbox"/> 6-10 years None.			01. N/A <input type="checkbox"/> Urgent <input type="checkbox"/> 1 year <input type="checkbox"/> 2 year			

Rev2008

Rev2008

Element Data

Element Group:	Embankments and Streams		Length:	-		
Element Name:	Streams and Waterways		Width:	-		
Location:			Height:	-		
Material:			Count:	1		
Element Type:			Total Quantity:	1 (all)		
Environment:	Benign / Moderate / Severe		Inspected:	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Limited <input type="checkbox"/>		
Protection System:						Perform. Deficiencies
Condition Data:	Units m ² / m / each / % / all	Exc.	Good	Fair	Poor*	
			1			00. None
Comments: Waterway is generally unobstructed with no evidence of scour.						
Recommended Work:			Maintenance Needs:			
None.			01. N/A			
			<input type="checkbox"/> Urgent <input type="checkbox"/> 1 year <input type="checkbox"/> 2 year			

Rev2008

Rev2008

Municipal Structure Inspection Form

MTO Site Number: 38S-234

Repair and Rehabilitation Required:		Priority				Estimated Construction Cost
Element	Repair and Rehabilitation Required	6 to 10 years	1 to 5 years	Within 1 year	Urgent	
Deck	Repairs to wearing surface across structure			X		\$5,000
Bearings	Repair bearing surface (SW corner of center span)			X		\$75,000
Approaches	Replace South wearing surface, replace guiderail		X			\$45,000
Trusses	Clean bearings, bottom chord and connections			X		Maintenance
Joints	Replace bridge deck seals/joints		X			\$40,000
Abutments/Piers	Partial depth concrete repairs		X			\$1,200,000
Beams/MLE	Reinforcing at section loss to webs			X		\$40,000
Steel Elements	Sand blasting, re-coat and steel repairs/upgrades		X			\$3,575,000
Total Cost						\$4,980,000

Associated Work:	Comments	Estimated Cost
Approaches:		
Detours:	Signage and Maintenance	\$10,000
Traffic Control:	By contractor (as required)	
Utilities:		
Right of Way:		
Environmental Study:	Environmental Study/Assessment	\$40,000
Other:	Eng. Design and Supervision (15%)	\$735,000
Contingencies:	20% Allowance	\$980,000
Total Cost		\$1,765,000

Justification:

General maintenance repairs to maintain service life of structure. Partial depth concrete removal and repairs to abutment walls and wingwalls is required if long term rehabilitation is the preferred option. The concrete repairs should be completed within 5 years. Re-coating of the steel elements and steel upgrades/ repairs to corroded areas is expected and should be phased as part of a large scale rehabilitation project. South approach wearing surface and guiderails should be replaced and hazard markers sign installed. Bridge, bearings and all truss elements should be cleared of all gravel/debris annually.

ADDITIONAL PHOTOS



Looking North Across Structure



Looking South Across Structure



West Elevation



East Elevation



Impact damage to inner surface of the top chord (~3.5m above bridge deck)



Severe spalling, delamination and map cracking with efflorescence (north abutment worse)